

ANNEXURE - C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION

CERTIFICATE No.00013/E7/2026

Dated: 04.08.2026

It is certified that an inspection team headed by **K. MOORTHY** BLOCK HEALTH SUPERVISOR, GOVERNMENT PRIMARY HEALTH CENTRE inspected the MAHARISHI VIDYA MANDIR - MANGADU, MANGALAM STREET, VASANTHAPURAM MAIN ROAD, MANGADU, CHENNAI - 600122 on **04.08.2026** and on the basis of Water Test report (Attached) bearing no **Lr.No29786/AEE/TWAD/DWTL/TVR** dated **13.07.2026** of Tamilnadu Water Supply and Drainage Board certified that the facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

This certificate is valid till **03.08.2027**

Signature : K. Moorthy

BLOCK HEALTH SUPERVISOR
Government Primary
Health Centre, Elichur,
Kancheepuram District

Seal :

Name: K. Moorthy

Designation : Block Health Supervisor
Government Primary Health Centre,
Ezhichur, Kundrathur Block,
Kancheepuram District.

To
MAHARISHI VIDYA MANDIR - MANGADU
MANAGALAM STREET, VASANTHAPURAM MAIN ROAD,
MANGADU, CHENNAI - 600122